

**TO BE FILLED BY THE INSPECTING OFFICER
(Assistant Engineer / Assistant Executive Engineer)**

	Name of the Officer,	LEKSHMI.O Assistant Engineer
1	Name of the School,	Al Huda Central School
2	Name of the Education District / Sub District,	Tirur, Kuttippuram
3	Location,	Malayil-Kadampuzha, Marakkara GP
4	Period for which the Certificate is issued,	2020-21
5	Types of Building,	Permanent RCC Building
a	Building size with Height ,	A Block GF : 1x6.17x9.95x3.60 1x11.73x6.23x3.60 4x6.15x6.23x3.60
	A Block FF : 1x6.17x9.95x3.60 1x4.30x3.25x3.60 5x6.15x6.23x3.60	A Block SF : 1x4.50x6.23x3.60 1x4.30x3.25x3.60 1x6.10x7.50x3.60 5x6.15x6.23x3.60
6	Nature of defect if any	
a	Foundation and Basement,	Nil
b	Superstructure,	Nil
c	Doors and Windows,	Nil
d	wood work wrought and put up,	Nil
e	Roof ,	Nil
f	Flooring,	Nil
g	Miscellaneous (Cracks if any),	Nil
7	Any major defects noticed which will render the building unsafe in any manner,	Not found at the time of inspection
8	Whether maintenance work have been done properly	Yes
9	Whether the structure is sound or not for conducting classes,	Sound under normal wind and weather conditions

Note :

- 1 The Stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.
- 2 Any additional observation deemed necessary for the Certificate , may be furnished separately with the Certificate

Certified that the school was inspected by me on 08/06/2020 and found to be fit/unfit to conduct classes for the period for the reasons stated above.

Place: Marakkara

Date: 08/06/2020



[Signature]
PRINCIPAL
AL HUDA CENTRAL SCHOOL
Malayil, P.O. Kadampuzha - 676553
Malappuram Dist, Kerala

[Signature]
Signature

Designation

Assistant Engineer
L.S.G.D SECTION
Marakkara Grama Panchayath

